ENGINEERING CHANGE NOTICE
DART AEROSPACE LTD

Date:	09.04.06	Job No.:	P00569	ADR Yes/No:	Yes	ADR Date:	09.04.06	ECN #:	09- 557
Product No.:	D350-567			Created By:	HS	Approved By:			
Product Name:	Vertical Reference Window			Checked By:		General Manager Approval:			

Distribution	Reqd	Resp	Initial / Date	Distribution	Reqd	Resp	Initial / Date
Production Manager	Y	LL	M 09.04.13	DQA / QA Coord	N		
Production Engineering Coord	Y	EC	M 09/04/08	QC Coordinator	N		
Production Document Control	Y	JLB	09/04/03	Marketing	N		
Customer Technical Support	Y	DS	09.04.13	Customer Order Processing	N		

Reason for Change:
Drawing revised because of interference with other parts.

Documents Affected:
D3294 Rev. C

PARTS MUST COMPLY [X]   PREVIOUS PARTS SATISFACTORY [ ]

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	N			
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N			
5	Update Product Compatability Matrix	N			
6	Create Eurocopter Form (FEE)	N			
7	Notify TC / FAA of Change	N			

#	Document Control Actions	Reqd	Resp	Notes	Complete
8	Move Electronic Files	Y	KJ		09.04.13
9	Update Blue/Pink/DSI Folder and Electronic Files	N			
10	Update Controlled PDF Files	Y	KJ		09.04.07
11	Update Master Document List (MDL)	Y	HS	MDL-D350-567 Rev. C	09.04.06 for HS
12	Update Document Record (DR)	Y	KJ	Rev. H	09.04.07
13	Update Product Development Summary	N			
14	Update QSI 021 and/or STC Approval List	N			
15	Update Parts / STC Database	Y	KJ		09.04.07
16	Update / Verify ARC Database	N			
17	Create / Update Change Record Form	Y	KJ		09.04.08
18	Create / Update PPP's	Y	KJ		09.04.13
19	Update Document Control Database / Laminated Dwgs	N			
20	Update Grey Project Binder	Y	KJ	Add ADR to D350-567 binder	09.04.07
21	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		09.04.07
22					
23					

Description / Action:
- D3294 revised due to un-anticipated interference with interior window.
- Part redesigned to incorporate DSI 9392
- Update estimate for production of D3294-1/-3/-5
- D350-567-115 now at CHG 004
- All D350-567-115 in stock should be updated to include D3294-1 per D3294 Rev. C
- Any D350-567-017/-027/-111 that include D350-567-115 should be updated to include D3294-1 per D3294 Rev. C

↳ CHG 005
↳ CHG 002
↳ CHG 002

ECN Verified & Complete: _____   Date: 09/04/24